



---

## Sanitary Sewer Overflow Report

10/16/2009

5:30 PM

---

Overflow Start:	10/16/2009	2:35 PM
Overflow End:	10/16/2009	4:30 PM

---

Location:	1990 DELK INDUSTRIAL BLVD
	Creek next to building

---

Primary Cause:	Pipe Failure
Secondary Cause:	Creek bank erosion
Estimated Volume:	9,200 Gallons
Waterway Affected:	Rottenwood Creek

---

Description Of Incident:	Creek bank erosion from recent rains caused a section of sewer main to fail allowing sewage to enter creek.
--------------------------	---

Description Of Response:	Marietta Water personnel quickly established a pump around to stop the escape and allow repairs to be completed. Sewer lines in the area are being examined for possible future relay to avoid similar problems in the future.
--------------------------	--

---

Contact:	Tim Marshall Environmental Compliance Coordinator Phone: 770-794-5229 Fax: 770-794-2286 email: tmarshall@mariettaga.gov
----------	---