



Sanitary Sewer Overflow Report

10/13/2009

8:50 AM

Overflow Start: 10/12/2009 11:00 AM
Overflow End: 10/12/2009 1:30 PM

Location: 566 HEYWARD CIR
ROW behind houses in this section of Heyward

Primary Cause: Capacity Failure
Secondary Cause: Wet Weather I/I
Estimated Volume: 2,550 Gallons
Waterway Affected: Noses Creek

Description Of Incident: Heavy sustained rainfall caused localized flooding and infiltration of sewer mains across much of the Marietta Water service area. Parts of our sewer system capacity were overcome causing manholes to overflow until floodwaters receded somewhat. Impact minimal.

Description Of Response: We are using these data for planning future improvements to our system.

Contact: Tim Marshall
Environmental Compliance Coordinator
Phone: 770-794-5229
Fax: 770-794-2286
email: tmarshall@mariettaga.gov