



Sanitary Sewer Overflow Report

11/14/2009

2:48 PM

Overflow Start:	11/14/2009	9:00 AM
Overflow End:	11/14/2009	12:59 PM

Location:	1754 SPINKS DR
	In ROW ditch by manhole just past power station

Primary Cause:	Blockage
Secondary Cause:	Grease
Estimated Volume:	9,600 Gallons
Waterway Affected:	Rottenwood Creek

Description Of Incident:	A partial grease blockage caused a sewer main to backup and relieve from a manhole. The overflow entered a storm drain draining to a tributary of Rottenwood Creek.
--------------------------	---

Description Of Response:	The blockage was relieved by hydrojet thus restoring normal service. The affected area was cleaned up, limed and deodorized. Sewer lines in the area will be cleaned and CCTV'd to examine for defects.
--------------------------	---

Contact:	Tim Marshall Environmental Compliance Coordinator Phone: 770-794-5229 Fax: 770-794-2286 email: tmarshall@mariettaga.gov
----------	---